<u>Road safety at Balgay Hill – an update</u> <u>#dundeewestend</u>



As residents may recall, some time ago, I discussed with officers in environment management at the City Council measures to improve safety on the roadway at Balgay Hill going up to the observatory. This included better signage of the 10 mph speed limit and better traffic management to protect pedestrians.

Progress with this has been delayed due to the COVID-19 health emergency but I recently asked for an update on the matter and have been given the following helpful feedback from the Service Manager – Environment at the City Council :

"I appreciate your understanding throughout the covid 19 emergency and would confirm that we remain outwith our normal service provision due to ongoing measures. Nevertheless, we have made some progress since we last exchanged emails. Our discussions with the City Engineers have led to a costed design for traffic calming measures in the form of speed bumps and additional signage along the road. It is our intention to progress the above works this financial year.

In the meantime, we will be arranging for the road to be swept again, to reveal the white paint is fully visible before the observatory is opened and traffic is permitted passed the gate.

We will also ensure the rock armour placement is correct which can be moved if necessary."