

## Haier to restart heat pump tumble dryer safety repair programme

OPSS has confirmed that Haier can begin an updated corrective action programme to address a fire safety risk that may not have been fixed by an earlier repair.