<u>School and contractor fined for unsafe</u> removal of asbestos

A school and its maintenance contractor have been fined after workers disturbed asbestos at the school while installing a new heating system.

Peterlee Magistrates' Court heard that, in February 2019, T.W. Steam & Heating Services Limited had been contracted by Park View Academy, to install a new heating system in the school building at Park View School, Chester Le Street.

In the course of the work, ceiling tiles containing asbestos were disturbed, potentially exposing several people to asbestos fibres.

An investigation by the Health and Safety Executive (HSE) found that the contractor and the school both failed to refer to existing asbestos registers and management plans to identify the presence of asbestos within the school building.

Park View Academy of Church Chare, Chester Le Street pleaded guilty to breaching sections 2(1) and 3(1) of the Health and Safety at Work etc. Act 1974 and was fined £3000 with £4785.37 costs.

T.W. Steam & Heating Services Limited of Rennys Lane Industrial Estate, Durham pleaded guilty to breaching sections 2(1) and 3(1) of the Health and Safety at Work etc. Act 1974 and was fined £2,000 with £4,710.37 costs.

Speaking after the hearing, HSE inspector Ashfaq Ali commented, "The dangers associated with asbestos are well known and advice and guidance is freely available from HSE and other organisations. Those in charge of premises have a duty to inform contractors of the presence of asbestos containing materials, ensuring that works are carried out safely.

"Those undertaking work which is likely to disturb asbestos, or asbestos containing materials, should ensure that building occupants and operatives are not exposed to asbestos. Those undertaking the work should also provide suitable information, instruction and training to their employees.

"Companies should be aware that HSE will not hesitate to take appropriate enforcement action against those that fall below the required standards."

- 1. The Health and Safety Executive (HSE) is Britain's national regulator for workplace health and safety. It aims to reduce work-related death, injury and ill health. It does so through research, information and advice, promoting training; new or revised regulations and codes of practice, and working with local authority partners by inspection, investigation and enforcement. www.hse.gov.uk
- 2. More about the legislation referred to in this case can be found at: www.legislation.gov.uk/
- 3. HSE news releases are available at http://press.hse.gov.uk

4. Further information about safely working with asbestos can be found at: https://www.hse.gov.uk/asbestos/

An investigation by the Health and Safety Executive (HSE) found that the contractor and the school both failed to refer to existing asbestos registers and management plans to identify the presence of asbestos within the school building.

Park View Academy of Church Chare, Chester Le Street pleaded guilty to breaching sections 2(1) and 3(1) of the Health and Safety at Work etc. Act 1974 and was fined £3000 with £4785.37 costs.

T.W. Steam & Heating Services Limited of Rennys Lane Industrial Estate, Durham pleaded guilty to breaching sections 2(1) and 3(1) of the Health and Safety at Work etc. Act 1974 and was fined £2,000 with £4,710.37 costs.

Speaking after the hearing, HSE inspector Ashfaq Ali commented, "The dangers associated with asbestos are well known and advice and guidance is freely available from HSE and other organisations. Those in charge of premises have a duty to inform contractors of the presence of asbestos containing materials, ensuring that works are carried out safely.

"Those undertaking work which is likely to disturb asbestos, or asbestos containing materials, should ensure that building occupants and operatives are not exposed to asbestos. Those undertaking the work should also provide suitable information, instruction and training to their employees.

"Companies should be aware that HSE will not hesitate to take appropriate enforcement action against those that fall below the required standards."

- 1. The Health and Safety Executive (HSE) is Britain's national regulator for workplace health and safety. It aims to reduce work-related death, injury and ill health. It does so through research, information and advice, promoting training; new or revised regulations and codes of practice, and working with local authority partners by inspection, investigation and enforcement. www.hse.gov.uk
- 2. More about the legislation referred to in this case can be found at: www.legislation.gov.uk/
- 3. HSE news releases are available at http://press.hse.gov.uk
- 4. Further information about safely working at height can be found at: https://www.hse.gov.uk/asbestos/

An investigation by the Health and Safety Executive (HSE) found that the contractor and the school both failed to refer to existing asbestos registers and management plans to identify the presence of asbestos within the school building.

Park View Academy of Church Chare, Chester Le Street pleaded guilty to breaching sections 2(1) and 3(1) of the Health and Safety at Work etc. Act 1974 and was fined £3000 with £4785.37 costs.

T.W. Steam & Heating Services Limited of Rennys Lane Industrial Estate, Durham pleaded guilty to breaching sections 2(1) and 3(1) of the Health and Safety at Work etc. Act 1974 and was fined £2,000 with £4,710.37 costs.

Speaking after the hearing, HSE inspector Ashfaq Ali commented, "The dangers associated with asbestos are well known and advice and guidance is freely available from HSE and other organisations. Those in charge of premises have a duty to inform contractors of the presence of asbestos containing materials, ensuring that works are carried out safely.

"Those undertaking work which is likely to disturb asbestos, or asbestos containing materials, should ensure that building occupants and operatives are not exposed to asbestos. Those undertaking the work should also provide suitable information, instruction and training to their employees.

"Companies should be aware that HSE will not hesitate to take appropriate enforcement action against those that fall below the required standards."

- 1. The Health and Safety Executive (HSE) is Britain's national regulator for workplace health and safety. It aims to reduce work-related death, injury and ill health. It does so through research, information and advice, promoting training; new or revised regulations and codes of practice, and working with local authority partners by inspection, investigation and enforcement. www.hse.gov.uk
- 2. More about the legislation referred to in this case can be found at: www.legislation.gov.uk/
- 3. HSE news releases are available at http://press.hse.gov.uk
- 4. Further information about safely working at height can be found at: https://www.hse.gov.uk/asbestos/