

# **Increased risks identified with Profemur cobalt chrome modular neck hip replacements**

Patients implanted with affected devices should expect to be contacted directly for a follow-up assessment, if required.