

Fine for company and director after employee falls through roof light

- HSE guidance says all work at height must be properly planned

A construction company and its director have been fined after a worker fell through the roof of a sheep barn.

Jack Croft, 30, suffered life changing injuries after the incident in Leyburn, North Yorkshire.

He was working for Norman Iveson Steel Products, as part of a project to extend the sheep barn. Roof sheets needed to be installed, bridging the gap between the old roof and new. Jack, from Bedale, was carrying out the work on 11 October 2022 when he stepped onto a fragile roof light which immediately broke under his weight. He fell from a height of around six metres.



Jack Croft fell through the barn roof light

Mr. Croft suffered significant life changing injuries, including five cranial fractures, 10 fractured ribs, a cranial bleed, hearing loss and fractures to his spine, eye socket, cheek, wrist and shoulder. He also suffered a collapsed left lung and a pulmonary embolism.

An investigation by the Health and Safety Executive (HSE) found the company had failed to implement basic working at height control measures, such as safety netting, to prevent falls from height in this area. The netting that was in place on site did not cover full work areas and was installed by persons without the sufficient skills to rig it. HSE also found a failure to plan, manage and monitor the construction phase, to ensure it was carried out in a safe manner.

HSE has a range of guidance on how to plan and carry out work at height safely: Construction – Work at height – HSE

Norman Iveson Steel Products Limited, of Hill Crest, North Yorkshire, pleaded guilty to Section 2(1) of the Health and Safety at Work etc. Act 1974. The company was fined £100,000 and ordered to pay costs of £6,101 at York Magistrates Court on 22 May 2025.

Phillip Iveson, a director of the company, pleaded guilty to Section 37 of the Health and Safety at Work etc. Act 1974 and fined £1,822 and told to pay costs of £2,358.

Speaking after the hearing, HSE inspector Gavin Carruthers, said: "This was a tragic incident where a young man narrowly escaped death but received life changing injuries. Falls from height continue to be the leading cause of workplace death in Great Britain and this incident was fully avoidable if steps were taken to address the risks."

This prosecution was brought by HSE enforcement lawyer Karen Park and paralegal officer Rebecca Withell.

Further information:

1. [The Health and Safety Executive](#) (HSE) is Britain's national regulator for workplace health and safety. We are dedicated to protecting people and places, and helping everyone lead safer and healthier lives.
2. More information about the [legislation](#) referred to in this case is available.
3. Further details on the latest [HSE news releases](#) is available.
4. Relevant guidance can be found here – [Construction – Work at height](#)
5. HSE does not pass sentences, set guidelines or collect any fines imposed. Relevant sentencing guidelines must be followed unless the court is satisfied that it would be contrary to the interests of justice to do so. The sentencing guidelines for health and safety offences can be found [here](#).