

Getting things done – Nethergate #dundeewestend



Residents have drawn to my attention that in Nethergate – north side, between Park Place and bus stop just west of that – one of the large pavement edging stones has been dislodged, probably by heavy vehicle.

As a result, a big hole has appeared between the stone and the pavement, which someone might easily put their foot into and twist their ankle.

I reported this to the council's Roads Maintenance Partnership and have received the following positive response :

"The Road Maintenance Partnership inspector for the area has raised an order to re-set the whin kerb at this location."