

Mine shaft collapse secured in Bishop Auckland

The Mining Remediation Authority acts quickly to protect people and the environment after hole appears overnight in farmer's field in County Durham.