<u>Serious operating irregularity at</u> <u>Romney Sands</u>



Romney Sands ticket office and station platform

At around 10:35 hrs on 28 August 2019, a train from Dungeness to Hythe left Romney Sands station and entered the single line section to New Romney. A train from Hythe to Dungeness was in the same section, travelling in the opposite direction. The two trains came to a stand about 316 metres apart.

We have undertaken a <u>preliminary examination</u> into the circumstances surrounding this incident. Having assessed the evidence which has been gathered to date, we have decided to publish a <u>safety digest</u>.

The safety digest will be made available on our website in the next few weeks.

Published 12 September 2019